


# CORNER RECORD

Agency Index CS2021-0008

Document Number \_\_\_\_\_

City of El Macero, Davis County of Yolo, CaliforniaBrief Legal Description Lot 61, El Macero Unit No. 1, Book 5 of Maps, at Pages 89-92**CORNER TYPE**

- Government Corner     Control  
 Meander                     Property  
 Rancho                         Other

Date of Survey September 2021**COORDINATES (Optional)**

N. \_\_\_\_\_ E. \_\_\_\_\_

Elevation \_\_\_\_\_

Units     Metric             U.S. Survey Foot

Horizontal Datum \_\_\_\_\_

Zone \_\_\_\_\_ Epoch Date \_\_\_\_\_

Vertical Datum \_\_\_\_\_

 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902PLS Act Ref.:     8765(d)             8771             8773             Other:Corner/Monument:     Left as found             Established             Rebuilt             Pre-Construction                                   Found and tagged         Reestablished             Referenced             Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:


 See sheet #2 for description(s):

Original 1 1/2" Iron Pipes per Book 5 of Maps, at Pages 89-92 were found at the rear angle points of said Map. Set 5/8" rebar with Plastic Cap LS 9236 at Southwest and Southeast corners of Lot 61.

Ramset nail was found in the curb on the projection of the easterly lot line of Lot 61. Like nails (or evidence of a missing nail) were found on both sides of N. El Macero Dr. on lot line projections.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on June 27, 2022Signed \_\_\_\_\_ P.L.S. or R.C.E. No. 9236**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received 10/21/2022and examined and filed 10/21/2022Signed [Signature] P.L.S. or R.C.E. No. 6878Title Yolo Co. Surveyor

County Surveyor's Comment \_\_\_\_\_



