CORNER RECORD				Agency Index		2022-3053	
City of	DDEA						
City of	BREA	C/L DOROTHY D			ORANGE	, California	
Brief Legal De	escription	C/L DOROTHY L	KIVE 130 ELT	OF WAI	NOWAN DRIVE		
		CORNER TYI		N	COORDINATES E.	· ·	
		ent Corner	Control	Elevation			
	Meander		Property	Units		U.S. Survey Foot	
	Rancho		Other		I Datum		
	D. ((0	veyAPRIL 06	3 2022		Epoch Date		
	Date of Sur	vey	, <u>2022</u>	Comp	atum olies with Public Resourd olies with Public Resourd	ces Code §§8801-8819	
PLS Act Ref:	8765(d)	8771	8773		☐ Othe	<u>.</u>	
Corner/	Left as found	Established	Rebuilt			onstruction	
Monument:	Found and tagged	Reestablished	Referenced			Construction	
	SURVEYO	R'S STATEMENT			SONAL	LAND D. SUS	
This Corner Reco	ord was prepared by me or	under my direction in c	onformance with		ROFF.	7	
the Professional L	_and Surveyors' Act on	ОСТОВІ	ER 10, 2022			S PR	
Signed	ANP SM	P.L.S. or R.C.E.	No. <u>8133</u>		Sign	8133	
	COUNTY SUR\	/EYOR'S STATEMEN	т	_		CALIFO	
This Corner Reco	ord was received	OCTOBER 11,	2022		Wased L	AND SUPL	
and examined an	d filed	APRIL 20, 20	23		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	R. AIL OR	

MONUMENT 1, TIED OUT ON PAGE 2, HAS NOT BEEN PROVEN TO BE AT THE CENTERLINE BEGINNING OF CURVE ON DOROTHY DRIVE 130' EAST OF WARDMAN DRIVE. FURTHER ANALYSIS WILL BE NEEDED TO PROVE THIS POSITION.


BPELSG-2016 Page 1 of 2

COUNTY SURVEYOR

County Surveyor's Comment

Signed

Title



MONUMENT NOTES

MONUMENT NOTES:

- 1 SEARCHED FOR SPIKE PER R1. FOUND NOTHING. <u>SET SPIKE & WASHER STAMPED</u> "LS 8133", FLUSH, PER TIES ON R1 AFTER CONSTRUCTION.
- 2 FD LEAD, TACK & TAG STAMPED "LS 8133", FLUSH IN CURB, PER R1, AFTER CONSTRUCTION.

THE PURPOSE OF THIS RECORD IS TO DOCUMENT THE PERPETUATION OF FOUND MONUMENT(S) PURSUANT TO THE PLS ACT SECTION 8771. NO CLAIM IS MADE REGARDING THE CORRECTNESS OF THE POSITION(S) OF SAID MONUMENTS(S), OR THE DIMENSIONAL RELATIONSHIP TO STREET CENTERLINES OR PROPERTY BOUNDARIES.

JN: 459-007/008