


CORNER RECORD

Agency Index _____
Document Number 9773

City of _____ County of El Dorado, California
Brief Legal Description Parcel 1 of the Parcel Map filed in Book 50 of Parcel Maps at Page 136

CORNER TYPE



T.9 N. R.9 E.

- Government Corner
- Meander
- Rancho
- Control
- Property
- Other

Date of Survey March 20, 2025

COORDINATES (Optional)

N. _____ E. _____
 Elevation _____
 Units Metric U.S. Survey Foot
 Horizontal Datum _____
 Zone _____ Epoch Date _____
 Vertical Datum _____
 Complies with Public Resources Code §§8801-8819
 Complies with Public Resources Code §§8890-8902

PLS Act Ref.: 8765(d) 8771 8773 Other:
 Corner/Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

Found monuments as noted on Sheet 2 along Business Drive Right of Way lines. Found Mag Nails & Shiners from Pre-Construction Corner Record. Re-establish position of 60P Nail (removed during construction) per Pre-Construction Corner Record with Lead Plug & Brass Tag, LS 5876 on the east Right of Way line of Business Drive.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on June 10, 2025
 Signed [Signature] P.L.S. or R.C.E. No. 5876



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 6/19/2025
 and examined and filed 6/26/2025
 Signed [Signature] P.L.S. or R.C.E. No. 9539
 Title DEPUTY SURVEYOR



County Surveyor's Comment

9-9-11-1

APN 109-401-006

